

Appendix HH
LORD · AECK · SARGENT
ARCHITECTURE

PHOTOGRAPHS

Date: May 15, 2012
Project: Heritage Center Site
By: Karen Gravel

file: c:\users\kg\desktop\h\heritage.docx

Remarks:



Front of Heritage Center – This is the eastern entrance of the building with what appear



The hallways appear to be in good condition. The lights are on.



Vegetation will need to be removed from around the building.



DSCN1338.JPG



Hallways appear to be in good condition.



The walkways are covered.



Western entrance



Northern end of the building.





There is a significant grade change from the rear of the building to the recreational area at the north end of the site.



This recreational area is similar to a large garden or park.




View of the recreational area.



View back to the building from the rear of the site.



Rear of the building



Stairs leading down to McDaniel School Park



Card readers appear to have been installed recently.



Significant utilities are located in the rear of the building and would need to be considered in any addition or site work.



The facility has a series of ramps from one end of the building to the other. The plan is an H form.



Air handling unit was operational on day of visit.



Air handling unit is sited between the major wings of the facility. Note gas meter to right.



Overall view of the northern recreational area. This is qualitatively a very nice outdoor space.



Northern end of western wing.



Utilities on site at rear of building



There are several trails around the perimeter of the site.



Recreational area at north end of the site. This is looking into the site from the northern edge. See following pictures.



Northern perimeter of site.



Northern perimeter and recreational area.



Recreational Area



There are several trails that connect the site to McDaniel School Park.